

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

002750" 64009960




Fig. 1






Fig. 2A

Fig. 3



002160" 64009960



002160" 64009960




Fig. 7




Fig. 8

Fig. 9




Fig. 10




Fig. 11





Fig. 12

002160" 64009960




Fig. 14





Fig. 13

002150" 64009960

Fig. 15



9/21

9/28

10









Fig. 16

002160" 64009960

Fig. 17



Reduce
1



002160" 6409960




Fig. 22




Fig. 24




Fig. 23




Fig. 25

002160" 64009960

FIG. 26





Fig. 28




Fig. 27

09650049-091200

Fig. 29





Fig. 30




Fig. 31




Fig. 40




Fig. 41

002760" 6409960

002160" 64009960




Fig. 32




Fig. 33




Fig. 34




Fig. 35



Fig. 36




Fig. 37

17/28

17/28




Fig. 38




Fig. 39

002760" 64009960

revise 7/2/90

18/28

18/28




Fig. 4.3

Reduce

19/28




Fig. 42




Fig. 44




Fig. 45

002260" 6409960

002150" 64009950




Fig. 46




Fig. 47




Fig. 48




Fig. 49




Fig. 50




Fig. 51




Fig. 52

002160" 64009960

23/28




Fig. 55

002160" 64009960

002160" 64009560






fig. 56


99
~~XX~~




~~Fig. 57~~
57




~~Fig. 58~~
58



~~Fig. 59~~
59



~~Fig. 60~~
60



~~Fig. 61~~
61




Fig. ~~61~~ 62






Fig. ~~62~~ 63

09660049, 091200



002160" 6409960




Fig. ~~45~~ 66




Fig. ~~46~~ 67




Fig. ~~47~~ 68

002160" 64009960